Declassified in Part - Sanitized Copy Approved for Release 2012/09/04: CIA-RDP78-03424A001400010019-7 WUNFILLENI 27 January 1954 MEMORANDUM TO FILE 25X1 FROM SUBJECT: Discrepancy in Contract XG-894; Project E-5250. Item MW 2054-22 of Contract XG-894 describes the multiplexing and patching facilities initially intended to be installed at 25X1 Division #2 of the system. This item reads as follows: 25X1 (a) Equipment now at to be removed and reinstalled 25X1 at this any additional material required to be supplied by the Contractor. Necessary patching facilities. Total item cost This cost, therefore, includes the materials necessary to modify the equipment removed from and re-installed at and the materials 25X1 involved in the patching facilities at 25X1 2. During the course of installation, it became evident that this equipment at was not available for relocation at ____. To solve our needs, 25X1 a similar type equipment was taken from a Stockpile system and was installed 25X1 at . This new equipment required no modification to fit our communications needs. 3. It becomes apparent, therefore, that the figure of \$1.042.92 should be reduced by the amount of the modification costs and Item MW 2054-22 should only include the cost of the patching facilities at This matta 25X1 was brought to the attention of but as yet there has been no action taken on the subject. 25X1 Project Engineer js DOG 16 BEY DATE 144/70 BY 37/69 ORIG COMP 33 OPI _______ TTPE _2 ORIG CLASS S PAGES REV CLASS

SECRET

CONFIDENTIAL

JUST ____ 22_ NEXT REV __ 2010 AUTH: HR TO-2